

Existing Pedestrian Facilities across Salisbury Road




2012.11.13 Walking Tour






[1] Location: MTR Exit near Kowloon Hotel



[2] Location: MTR Subway underneath Middle Road (1)



[3] Location: MTR Subway underneath Middle Road (2)



[4] Location: Subway underneath Salisbury Road (1)



[5] Location: Subway underneath Salisbury Road (2)



[6] Location: Subway underneath Salisbury Road (3)




[7] Location: Subway Exit/Entrance at Sogo (1)



[8] Location: Subway Exit/Entrance at Sogo (2)




[9] Location: Hong Kong Cultural Centre opposite Star House




[10] Location: Ground Level Crossing to Canton Road



[11] Location: Subway Entrance at Hong Kong Cultural Centre (1)



[12] Location: Subway Entrance at Hong Kong Cultural Centre (2)




[13] Location: Within Salisbury Subway connecting HKCC (1)




[14] Location: Within Salisbury Subway connecting HKCC (2)




[15] Location: Subway Entrance/ Exit at YMCA




[16] Location: Middle Road near Kowloon Hotel



[17]Location: Nathan Road near The Peninsula Hotel



[18] Location: Junction of Salisbury Road and Nathan Road(1)



[19] Location: Junction of Salisbury Road and Nathan Road(2)




[20] Location: Subway underneath Sheraton Hotel (1)



[21]Location: Subway underneath Sheraton Hotel (2)



[22] Location: Subway underneath Sheraton Hotel (3)



[23] Location: Subway Entrance/Exit at Peninsular Hotel

Summary of Concerns from Members

- There is room for improving pedestrian signages at ground level footways and subways leading to the waterfront.
- The pedestrian signages and coding at the different subway sections (managed by different parties) should be more consistent and better coordinated.
- There is room for improving the annotation of information maps within the subways. Pictures of popular destinations may be used to replace unfamiliar names in the maps.

Pedestrian Connectivity in Tsim Sha Tsui Waterfront Summary of Concerns from Members (Cont.)

- Present subway from Nathan Road to the waterfront is not a straight route. The option of resuming atgrade crossing across Salisbury Road should be explored.
- A more comprehensive walking map should be produced to cover at-grade footways and subways managed by both government and non-government bodies.

Follow-Up

Government will continue to -

- review the pedestrian signages in phases firstly for the ground level; and secondly for within the subways, with a view to providing clearer information to pedestrians to get to the waterfront.
- liaise among departments and different management agents for various sections of the subways such as MTRCL as well as private developers with a view to improving the pedestrian signage system holistically.

Thank You